Section Attachments

Event ID Q23003
Event Name Surface Grinder
Section Name Standard Line Item Pricing
Section Description SPECIFICATIONS:

Machine Tool Diagnostics, Inc. \$ 14,910.00
Taza Supplies DBA Tiles in Style \$ 22,778.60
Technology International, Inc. \$ 19,120.00
Horizon Technologies, LLC \$ 17,135.40

Cumpling Name	Posnense Notes	Itam/Comics (Bossined Entity)	Quantitud	Linit Did	Drice /Dee	Extended Rid Ruis	Notes	CumplicyNotes	Attachments	NoDia
Machine Tool Diagnostics, Inc.	Machine Estimate is Attached.	Item/Service (Required - Entity) Chevalier FSG618M			8,970.00	\$ 8,970.0		Package discount is \$2,230 in total.	Attachments	NoBid No
Taza Supplies DBA Tiles in Style	FSG-618M Chevalier Manual Surface	Chevalier FSG618M	1	\$ 1	16,016.00	\$ 16,016.0	0			No
Technology International, Inc.	***Please see our Equipment Proposal TII/IL/0323/27039 attached.	Chevalier FSG618M	1	\$ 1	13,500.00	\$ 13,500.0	0	***Please see our Equipment Proposal TII/IL/0323/27039 attached.		No
Horizon Technologies, LLC	all	Chevalier FSG618M	1	\$ 1	12,108.00	\$ 12,108.0	0			No
Machine Tool Diagnostics, Inc.	Machine Estimate is Attached.	Kanetsu or Chevalier 6" x 18" Chuck	1	\$	1,200.00	\$ 1,200.0	0			No
Taza Supplies DBA Tiles in Style	FSG-618M Chevalier Manual Surface	Kanetsu or Chevalier 6" x 18" Chuck	1	\$	1,372.00	\$ 1,372.0	0			No
Technology International, Inc.	***Please see our Equipment Proposal TII/IL/0323/27039 attached.	Kanetsu or Chevalier 6" x 18" Chuck	1	\$	1,450.00	\$ 1,450.0	0			No
Horizon Technologies, LLC	all	Kanetsu or Chevalier 6" x 18" Chuck	1	\$	1,296.00	\$ 1,296.0	0			No
Machine Tool Diagnostics, Inc.	Machine Estimate is Attached.	LED Machine Lamp	1	\$	200.00	\$ 200.0	0			No
Taza Supplies DBA Tiles in Style	FSG-618M Chevalier Manual Surface	LED Machine Lamp	1	\$	230.00	\$ 230.0	0			No
Technology International, Inc.	***Please see our Equipment Proposal TII/IL/0323/27039 attached.	LED Machine Lamp	1	\$	240.00	\$ 240.0	0			No
Horizon Technologies, LLC	all	LED Machine Lamp	1	\$	216.00	\$ 216.0	0			No
Machine Tool Diagnostics, Inc.	Machine Estimate is Attached.	Wheel Hub (Flange and weights)	1	\$	125.00	\$ 125.0	0			No
Taza Supplies DBA Tiles in Style	FSG-618M Chevalier Manual Surface	Wheel Hub (Flange and weights)	1	\$	145.00	\$ 145.0	0			No
Technology International, Inc.	***Please see our Equipment Proposal TII/IL/0323/27039 attached.	Wheel Hub (Flange and weights)	1	\$	150.00	\$ 150.0	0			No
Horizon Technologies, LLC	all	Wheel Hub (Flange and weights)	1	\$	135.00	\$ 135.0	0			No
Machine Tool Diagnostics, Inc.	Machine Estimate is Attached.	Crossfeed & Elevating Digital Readout	1	\$	2,580.00	\$ 2,580.0	0			No
Taza Supplies DBA Tiles in Style	FSG-618M Chevalier Manual Surface	Crossfeed & Elevating Digital Readout	1	\$	2,948.60	\$ 2,948.6	0			No
Technology International, Inc.	***Please see our Equipment Proposal TII/IL/0323/27039 attached.	Crossfeed & Elevating Digital Readout	1	\$	3,780.00	\$ 3,780.0	0			No
Horizon Technologies, LLC	all	Crossfeed & Elevating Digital Readout	1	\$	2,786.40	\$ 2,786.4	0			No
Machine Tool Diagnostics, Inc.	Machine Estimate is Attached.	Readout Installation	1	\$	550.00	\$ 550.0	0			No
Taza Supplies DBA Tiles in Style	FSG-618M Chevalier Manual Surface	Readout Installation	1	\$	-	\$		INCLUDED IN ABOVE		No
Technology International, Inc.	***Please see our Equipment Proposal TII/IL/0323/27039 attached.	Readout Installation	1	\$	-	\$				No
Horizon Technologies, LLC	all	Readout Installation	1	\$	594.00	\$ 594.0	0			No
Machine Tool Diagnostics, Inc.	Machine Estimate is Attached.	Freight, Installation, & Other Charges	1	\$	1,285.00	\$ 1,285.0	0			No
Taza Supplies DBA Tiles in Style	FSG-618M Chevalier Manual Surface	Freight, Installation, & Other Charges	1	\$	2,067.00	\$ 2,067.0	0	DRO INSTALLATION CHARGES:DOUBLE AXIS		No
Technology International, Inc.	***Please see our Equipment Proposal TII/IL/0323/27039 attached.	Freight, Installation, & Other Charges	1	\$	-	\$				No
Horizon Technologies, LLC	all	Freight, Installation, & Other Charges	1	\$	-	\$				No